



# CHINASTARS

REFLECTIVE MATERIAL

## TECHNICAL DATA SHEET

*BE SEEN, BE SAFER*

### BLACK SOFT REFLECTIVE FABRIC CSR-6201

#### DESCRIPTION

Chinastars black soft reflective fabric CSR-6201 is composed of wide angle exposed retro reflective glass beads bonded to a soft polyester cloth backing with black adhesives. It helps enhance the visibility of wearer at nighttime when illuminated by a light source. CSR-6201 is soft and light-weighted, can be easily incorporated into any fashion collections where high visibility and soft hand feeling are both required.

#### SPECIFICATION

Fabric Backing	Composition	Daytime Color	Weight	Width	Reflectivity <sup>1</sup>
100% Polyester	Base fabric=21% Bonding resin=26% Glass beads=53%	Black	205±15g/m <sup>2</sup>	140cm	Around10

<sup>1</sup> Measured on new product at +5.0° entrance and 0.2° observation angles.

#### CARE AND MAINTENANCE INSTRUCTIONS

Actual life of reflective pattern printing fabric depends on cleaning method and wear conditions.



Do not presoak  
Machine wash warm,  
40°C (105°F)



Tumble  
dry low



Cool iron, Do  
not exceed  
120°C (248°F)



Do not bleach



Do not  
dry-clean

Some suggestions for extending the life of reflective fabric:

1. When do machine wash, you may use a mild detergent, but No Bleach or Fabric Softener!
2. Try to avoid wash the reflective products with your work jeans or any clothing with rough fabric or edges. The microscopic glass beads on the reflective fabric can be worn off by rough texture.
3. Try to line dry your reflective products. If you choose to machine dry, try to remove the product immediately. The added heat can damage the reflective fabric.

#### HANDLING PRECAUTIONS

1. Our reflective fabric is composed of aluminum coated micro-glass beads. The aluminum layer is easily damaged in acid, alkali or humid environment which on one hand will influence the retro reflective performance of our reflective fabric, and on the other hand will cause possible color difference and expose the base fabric.  
Do not drip or wipe the surface of reflective fabric with acid or alkali. Avoid soak in acid or alkaline solutions for long time.

2. Store in a cool, dry and ventilated place below 26.7 °C (80 °F) and lowering than 70% relative humidity..
3. Try to avoid using water-cooled air conditioner in manufacturing process.
4. We strongly recommend all workers wear gloves during garment manufacturing, to avoid possible blemishes caused by sweat. Meanwhile, try to avoid direct contact with machine oil or other corrosive liquids.
5. If possible, try to replace the metal machine presser with plastic one to reduce friction on reflective surface in sewing process.
6. Try to slow down when sewing on thicker part to avoid possible abrasion on the surface of reflective fabric.
7. Reflective fabric shall be handled with care during production and try to avoid abrasion with sharp objects.
8. Finished reflective products are recommended to be dried or dehumidified before packing.
9. Reflective fabric sewed on garment scuff or edge of zipper is susceptible to friction and easy to wear.
10. Before sewing, try to pinpoint the sewing line, and avoid sewing and removing repeatedly. Otherwise, the obvious pinhole might affect the garment appearance.



**HANGZHOU CHINASTARS REFLECTIVE MATERIAL CO., LTD**

Office: No.98 Shimin Street,Jiangan District,  
Hangzhou,China,310016  
Tel: +86-571-88155512  
Fax: +86-571-88156171  
Website: [www.chinareflective.com](http://www.chinareflective.com)  
Email: [info@chinastars.com.cn](mailto:info@chinastars.com.cn)

**Hangzhou Factory:**  
Jingshan Town,  
Yuhang district,  
Hangzhou,China

**Huzhou Factory:**  
Southern Industrial  
Park, Changxing  
county, Huzhou,China

*BE SEEN , BE SAFER*